

보일러용 고강도 T23강의 용접부 손상 원인 분석

박기덕^a, 안종석^b 신동혁^c, 이창희^a

^a한양대학교 신소재공학부

^b한국동서밸전(주) 발전처

^c한양대학교 재료화학공학부

Diagnosis of cracking in T23 welds for power plant application

Kiduck Park ^aJongsuk Ahn^a, Donghyeak Shin^a, Changhee Lee^a,

^a Div. of Mater. Sci. and Eng., Hanyang Univ., 17 Haengdang-dong, Seongdong-gu, Seoul
133-791, Korea

^bPower Generation Dept. Korea East-West Power Co., Ltd Seoul 135-791, Korea

^cDiv. of Mater. and Chem. Eng., Hanyang Univ., 1271 Sa-3 dong, Sangnok-ku, Ansan,
kyouenggi-do, 425-791, Korea

Abstracts

This paper has been performed in order to figure out the reason of failure in T23 weldments used for boiler tube at 550 °C. Defects such as cracks and cavities occurred in CGHAZ (coarse grain heat-affected-zone) and multi pass of weld metal, and these crack propagated along grain boundary. Microstructure evolution such as grain growth and carbide precipitation was investigated by optical microscope (OM), transmission electron microscope(TEM). Moreover, Auger electron spectroscope (AES) was employed in order to examine segregation along the grain boundaries. There is significant difference in grain size and precipitation distribution in the region where cracking took place. In addition, sulfur segregation was observed. Based on the results of this investigation, it has been possible to establish that this type of cracks were consistent with reheat cracking and creep damage. Selection of optimal filler metal, heat input, and PWHT temperature is required for prevention in order to avoid this type of cracking.

Key Words : T23, Weldments, PWHT Cracking, Precipitation, Segregation