



5 Minute Safety Meeting

for the foreign workers

Forklift Truck Work

A. Dangers in Forklift Truck Work

- Dangers of contact of the worker with forklift truck.
- Dangers of failing load.
- Turnover or fall of forklift truck.

Danger	Reason
Dangers of contact of the worker with forklift truck	<ul style="list-style-type: none"> • Overspeed driving in narrow pathway. • Reverse driving. • Blocking of the driver's sight by over-loading.
Dangers of falling load	<ul style="list-style-type: none"> • Unstable loading. • Sudden start/stop/turn. • Unexperienced driving.
Turnover or fall of forklift truck	<ul style="list-style-type: none"> • High speed turn. • Slant of the floor at workplace. • Unsafe pathway surface. • Overloading.

B. Safety in Forklift Truck Work

- Do not load exceeding the limit.
- Keep the stability of the forklift truck while conveying or driving.
- Keep the speed limit.
- Do not make speedy turn.
- Do not drive or turn with the load raised.
- Use the pallet or skid suitable for the handling load.

지게차 작업 안전

A 지게차의 위험요소

- 지게차와 작업자간 접촉위험
- 화물의 낙하 위험
- 지게차 자체의 전도, 전락 위험

위험성	원인
지게차와 작업자의 접촉위험	<ul style="list-style-type: none"> • 좁은 통로를 과속으로 운전 • 차량 후진시 • 화물 과적으로 운전자의 시야가림
화물의 낙하위험	<ul style="list-style-type: none"> • 불안정한 화물의 적재 • 급출발/급정지/급선회 • 미숙한 운전조작
차량의 전도, 전락	<ul style="list-style-type: none"> • 고속 급선회 • 작업장 바닥의 경사 • 불안정한 통로면 • 화물의 과적재

B 지게차의 안전작업

- 적재하중을 초과하여 적재하여서는 안된다.
- 운반, 주행시 지게차의 안정도를 유지한다.
- 지게차의 제한 속도를 지켜 운행하여야 한다.
- 급속한 급선회를 하지 않아야 한다.
- 화물을 높게 들어올린 상태로 주행이나 선회를 하여서는 안된다.
- 취급하는 화물에 적합한 파레트 또는 스키드를 사용하여야 한다. 