

# 5 Minute Safety Meeting

## for the foreign workers

### GENERAL SAFETY RULES ON MACHINERY

-기계일반 안전수칙-

#### Safety on Tools

- Striking part of the chisel should be maintained of its rechangular shape, broken or loosen handles should be replaced.
- Keep the tools in the designated place.
- Tools with sharp edge should be stored with the cover or in a box.
- Wear the safety goggles, if the pieces can be spattered to your eyes.

#### Safety on Drilling Work

- Verify that the drill is properly tightened, before use.
- Do not wear the gloves while drilling.
- Do not fix the table after rotating the drill.
- Neither blow the chips with your mouth nor remove them with hand, while rotating the drill.
- Make a small hole first for big size hole.
- Put a wooden plate below as a base, when drilling a hole into a thin place.
- Make sure the drill is electrically grounded before use.

#### 수공구 안전수칙

- 정이나 끌과 같은 기구는 때리는 부분이 버섯모양 같이 되면 정비하고, 자루가 망가지거나 헐렁하면 교체하여야 한다.
- 수공구는 사용한 후에는 일정한 보관장소에 넣어 보관하여야 한다.
- 끝이 예리한 수공구는 덮개나 보관함에 넣어서 보관하여야 한다.
- 파편이 될 위험이 있는 작업에는 보안경을 착용하여야 한다.

#### 드릴작업 안전수칙

- 사용하기 전에는 드릴이 올바르게 고정되어 있는지 확인하여야 한다.
- 장갑을 끼고 작업하지 않아야 한다.
- 드릴을 회전시킨 후에는 테이블을 고정하지 않아야 한다.
- 드릴회전 중에는 칩을 입으로 불거나 손으로 제거하지 않아야 한다.
- 큰 구멍을 가공할 때에는 먼저 작은 구멍을 가공한 다음에 큰 구멍을 가공한다.
- 얇은 판에 구멍을 가공할 때는 나무판을 밑에 깔고 작업을 한다.
- 전기드릴을 사용할 경우에는 접지한 후 사용하여야 한다.