Original Article

J Trauma Inj 2023;36(3):196-205 https://doi.org/10.20408/jti.2023.0026



Clinical characteristics of patients with the hardware failure after surgical stabilization of rib fractures in Korea: a case series

Na Hyeon Lee, MD¹⁽¹⁾, Sun Hyun Kim, MD¹⁽¹⁾, Seon Hee Kim, MD¹⁽¹⁾, Dong Yeon Ryu, MD¹⁽¹⁾, Sang Bong Lee, MD¹⁽¹⁾, Chan Ik Park, MD¹⁽¹⁾, Hohyun Kim, MD¹⁽¹⁾, Gil Hwan Kim, MD¹⁽¹⁾, Youngwoong Kim, MD²⁽¹⁾, Hyun Min Cho, MD³⁽¹⁾

¹Department of Trauma and Surgical Critical Care, Biomedical Research Institute, Pusan National University Hospital, Pusan National University School of Medicine, Busan, Korea

²Department of Thoracic and Cardiovascular Surgery, National Medical Center, Seoul, Korea

³Department of Trauma Surgery, Cheju Halla General Hospital, Jeju, Korea

Purpose: Surgical stabilization of rib fractures (SSRF) is widely used in patients with flail chests, and several studies have reported the efficacy of SSRF even in multiple rib fractures. However, few reports have discussed the hardware failure (HF) of implanted plates. We aimed to evaluate the clinical characteristics of patients with HF after SSRF and further investigate the related factors.

Methods: We retrospectively reviewed the electronic medical records of patients who underwent SSRF for multiple rib fractures at a level I trauma center in Korea between January 2014 and January 2021. We defined HF as the unintentional loosening of screws, dislocation, or breakage of the implanted plates. The baseline characteristics, surgical outcomes, and types of HF were assessed.

Results: During the study period, 728 patients underwent SSRF, of whom 80 (10.9%) were diagnosed with HF. The mean age of HF patients was 56.5±13.6 years, and 66 (82.5%) were men. There were 59 cases (73.8%) of screw loosening, 21 (26.3%) of plate breakage, 17 (21.3%) of screw migration, and seven (8.8%) of plate dislocation. Nine patients (11.3%) experienced wound infection, and 35 patients (43.8%) experienced chronic pain. A total of 21 patients (26.3%) underwent reoperation for plate removal. The patients in the reoperation group were significantly younger, had fewer fractures and plates, underwent costal fixation, and had a longer follow-up. There were no significant differences in subjective chest symptoms or lung capacity.

Conclusions: HF after SSRF occurred in 10.9% of the cases, and screw loosening was the most common. Further longitudinal studies are needed to identify risk factors for SSRF failure.

Keywords: Bone fractures; Bone screws; Flail chest; Reoperation; Ribs

INTRODUCTION

Received: April 26, 2023

Accepted: June 14, 2023

Department of Trauma and Surgical

Critical Care, Biomedical Research

Institute, Pusan National University Hospital, Pusan National University

School of Medicine, 179 Gudeok-ro,

Seo-gu, Busan 49241, Korea Tel: +82-51-240-7369

Email: ksh810427@gmail.com

Revised: June 7. 2023

Correspondence to

Seon Hee Kim, MD

Background

Multiple rib fractures are the most common injuries observed af-

ter blunt chest trauma and account for approximately 10% of all trauma cases [1]. As rib fractures are frequently accompanied by major intrathoracic and extrathoracic injuries, they are inevitably associated with severe damage, pain, and long-term sequelae [2–

© 2023 The Korean Society of Traumatology

This is an Open Access article distributed under the terms of the Creative Commons Attribution Non-Commercial License (http://creativecommons.org/licenses/by-nc/4.0/) which permits unrestricted non-commercial use, distribution, and reproduction in any medium, provided the original work is properly cited.

4]. Furthermore, more fractured ribs and older age were associated with poorer outcomes [5,6]. Insufficient ventilation and impaired pulmonary hygiene due to pain can lead to critical respiratory complications in these patients. Pain control, respiratory support, and pulmonary rehabilitation are the standard therapies for rib fractures, conventionally [1]. However, over the past few decades, there has been emerging interest in the surgical stabilization of rib fractures (SSRF) with technological advancements in surgical instruments. Previous randomized studies have demonstrated that SSRF reduces the duration of hospital stay, ventilator days, the occurrence of pneumonia, and mortality in patients with flail chest [7–9]. Recent trials on chest wall injuries have shown favorable outcomes in terms of pain and disability-related quality of life among patients with a nonflail chest [10]. Throughout the literature supporting the advantages of SSRF, the indications for SSRF have expanded, and SSRF is now becoming an established technique at regional trauma centers [11-13].

As the use of SSRF increases, concerns regarding surgical complications have inevitably been raised. To stabilize a fractured rib, SSRF usually involves nonabsorbable metallic implants. Unlike other bones, the ribs continue to move while breathing after orthopedic surgery, which can contribute to long-term complications. Recent studies have reported an incidence of up to 10% for complications, including bleeding, infection, inadequate bone healing, implant-related irritation, and implant failure [14]. Despite the assumption of relative safety, little is known about the long-term complications of SSRF, particularly those associated with hardware failure (HF) of the implanted plates. HF is defined as the unintentional loosening of screws, dislocation, or breakage of implanted plates and can occur for various reasons, such as improper placement, insufficient screw fixation, or a lack of plate length [15]. Previous studies have investigated the efficacy of SSRF and its associated risks; however, few have explored the clinical characteristics and factors related to HF after SSRF [14-18]. Understanding the clinical characteristics and risk factors of HF can help improve patient selection, surgical techniques, and postoperative care, which may reduce the incidence of complications and improve patient outcomes.

Objectives

In this study, we aimed to retrospectively analyze the electronic medical records of patients who underwent SSRF for multiple rib fractures at a level I trauma center in Korea to assess the clinical characteristics of patients with HF and further investigate the factors related to reoperation. We hypothesized that HF after SSRF is not prevalent and typically has insignificant clinical consequences.

METHODS

Ethics statement

This study was approved by the Ethics Committee of Pusan National University Hospital (No. H-2205-007-114). The requirement for informed consent was waived due to the retrospective nature of the study. The study was conducted in accordance with the Declaration of Helsinki for experiments involving humans.

Study setting and populations

This retrospective cohort study was performed at a regional trauma center between January 1, 2014 and January 1, 2021. Using the hospital inpatient inquiry system, 5,792 patients with chest injuries admitted to the level I trauma center were identified. We selected patients who had undergone surgical fixation of the chest wall. A total of 728 patients who underwent SSRF were included in the study. The exclusion criteria were as follows: no HF, age < 16 years, death within 48 hours after surgery, and follow-up duration < 30 days. The final study population comprised 80 patients with HF after SSRF (Fig. 1).

Data collection

Patient demographics, mechanisms of injury, and SSRF and HF characteristics were recorded. The available data included age, sex, mechanism of injury, Injury Severity Score (ISS), anatomical




Fig. 1. Flowchart of the study.

JTI

features of the chest wall injuries (flail chest, bilateral fracture, sternal fracture, number of rib fractures, costal fractures), HF, location, failed plating system, failure mode, time to detection of HF, surgical details (such as fixation site, number of plates implanted, fixed rib number, and time to SSRF), any postoperative complication, reoperation, hospital stay, laboratory values of pulmonary function, follow-up duration, and survival status. In addition, a subgroup analysis was performed by dividing the patients into two groups according to whether metal removal was performed.

Definition of anatomic location chest wall injury

The consensus of the Chest Wall Injury Society (CWIS) was used to describe the location of rib fractures [19]. The chest wall was defined as having three sectors: the anterior, lateral, or posterior sector. These were divided by the anterior and posterior axillary lines, where the anterior axillary line defined the border between the anterior and lateral fractures and the posterior axillary line defined the border between the lateral and posterior fractures. In addition to these three sectors, the costal cartilage sector was recorded. A flail segment was defined as three or more consecutive ribs that fractured in more than one location, producing a free-floating segment of the chest wall.

Type of chest wall plating system

During the study period, four thoracic surgeons performed SSRF using at least one of four commercially available plating systems, all of which were anterior bicortical screw locking systems: SternaLock Blu Plate (Zimmer Biomet Inc), ARIX Sternal & Rib System (Jeil Medical Corp), APIS Rib Locking Plate System (TDM Corp), and MatrixRIB Fixation System (Depuy Synthes) (Fig. 2). All the systems included straight or precontoured titanium plates and self-drilling and self-tapping screws, except for the Matrix-RIB Plate. The choice of plating system was at the discretion of the surgeon.

Definition of HF mode

HF was defined as follows: (1) screw loosening, defined as a screw that protrudes from the screw hole but does not pull out completely; (2) screw migration, defined as a screw being pulled out of a screw hole and moved to a completely different position; (3) plate fracture, defined as breakage of implanted plates; and (4) plate dislocation, defined as the displacement of a plate superiorly or inferiorly (Fig. 3).

HF detection

All patients visited the hospital regularly at 3, 6, and 12 months




Fig. 2. Type of chest wall plating system. (A) SternaLock Blu Plate (Zimmer Biomet Inc). (B) ARIX Sternal & Rib System (Jeil Medical Corp). (C) APIS Rib Locking Plate System (TDM Corp). (D) MatrixRIB Plate (Depuy Synthes).




Fig. 3. Failure modes of the implanted plates and screws. (A) Screw loosening: protrusion of the screw from the screw hole (black arrow) but does not pull out completely. (B) Screw migration: completely pulled out the screw from the screw hole and moved away to different positions (black arrows). (C) Plate fracture: breakage of implanted plates (white arrows). (D) Plate dislocation: displacement of a plate in the superior or inferior direction from normal alignment (white arrow).

after surgery. Three-dimensional chest computed tomography (CT), pulmonary function tests, and chest radiography were routinely performed. HF was confirmed using routine imaging after surgery.

Outcome measure

The primary objective of this study was to report the incidence, characteristics, and clinical impact of HFs. The secondary objective was to determine the differences between patients who underwent reoperation (the plate removal surgery group) and those who did not.

Statistical analysis

Summary statistics are reported as median and interquartile range (IQR) or mean ± standard deviation, where appropriate. Categorical variables are expressed as numbers and percentages. Chi-square and Fisher exact tests were used to compare the frequencies of categorical variables between the groups. The Mann-Whitney U-test and Wilcoxon rank-sum test were used to compare the mean values of continuous variables. We used the receiver operating characteristic (ROC) curve and area under the curve (AUC) to evaluate predictive factors for plate removal. A P-value of <0.05 was considered statistically significant. Statistical analysis was performed using IBM SPSS ver. 22 (IBM Corp).

RESULTS

Characteristics of the patients with HF

The demographic characteristics of patients with HF are summarized in Table 1. The overall incidence of HF after SSRF was 10.9% (80 of 728). The mean age of HF patients was 56.5 ± 13.6 years, with the most common mechanism being motor vehicle accidents (57.5%). The median number of fractured ribs per patient was 9 (IQR, 4–24) and 73.8% of the patients had a flail segment. The median ISS was 22 (IQR, 4–45), indicating a severe injury. In terms of comorbidities, the majority of patients (68.6%) had no underlying disease, whereas those with diabetes mellitus (2.5%) had ischemic heart disease.

SSRF was performed within 7.5 days by four thoracic surgeons with SSRF experience ranging from 1 to more than 10 years. At least one of the four commercially available plating systems was chosen for the SSRF, with the most commonly used system being ARIX (62.5%), followed by the SternaLock (41.3%), APIS (22.5%), and MatrixRIB (3.8%). An average of four ribs (IQR, 1–13) were fixed, and six plates (IQR, 1–29) were implanted. SSRF was mainly performed anterolaterally (anterior, 52.5%; lateral, 72.5%; and posterior, 43.8%). This is consistent with the most common location of HF.

Although no deaths were reported during hospitalization, perioperative complications such as pneumonia (51.2%), acute

JTI

Table 1. Clinical characteristics of the paties	ents included in the study
---	----------------------------

Characteristic	Value (n=80)
Demographic	
Age (yr)	56.5±13.6
Male sex	66 (82.5)
Mechanism of injury	
Motor vehicle accident	46 (57.5)
Fall	24 (30.0)
Crush injury	9 (11.3)
Penetrating injury	1 (1.3)
Injury severity	
Injury Severity Score	22 (4-45)
Flail segment	59 (73.8)
Bilateral rib fracture	31 (38.8)
Sternal fracture	14 (17.5)
No. of rib fractures	9.3±4.8
Surgical procedure	
Time from admission to SRF (day)	7.5 ± 6.4
No. of fixed ribs	$4.4{\pm}2.0$
No. of implanted plates	6.6±4.2
Fixation of costal cartilage	14 (17.5)
Fixation sector of chest wall	
Anterior	42 (52.5)
Lateral	58 (72.5)
Posterior	35 (43.8)
Sternum	12 (15.0)
Complication	
Wound infection	9 (11.3)
Pneumonia	41 (51.2)
Acute kidney injury	13 (16.3)
Tracheostomy	29 (36.3)
Hospital stay (day)	52.0 ± 66.1
Patients' follow-up	
Follow-up duration (day)	358.6±291.3
Subjective chest symptom	41 (51.2)
FVC ≥80% predicted	32 (40.0)
Plate removal operation	21 (26.3)

Values are presented as mean±standard deviation, number (%), or median (interquartile range).

SRF, surgical rib fixation; FVC, functional vital capacity.

kidney injury (16.3%), and wound infection (11.3%) occurred. Thirty-five patients (43.8%) experienced chronic pain during follow-up. Thirty-two patients (40.0%) presented with normal lung capacity at the last follow-up. A total of 21 patients (26.3%) underwent reoperation for plate removal.

Clinical features of HF in total cohort

The clinical features of patients with HF are shown in Table 2. The mean time from implantation to HF was approximately 3 months. HF was detected in the anterolateral region of the chest Table 2. Clinical features of hardware failure

Clinical feature	Value (n=80)
Time to detection of hardware failure (day)	84.0±131.2
Failure location	
Anterior	28 (35.0)
Lateral	35 (43.8)
Posterior	18 (22.5)
Sternum	7 (8.8)
Failed plating system ^{a)}	
SternaLock	27 (33.8)
ARIX	45 (56.3)
APIS	10 (12.5)
MatrixRIB	1 (1.3)
Failure mode	
Screw loosening	59 (73.8)
Screw migration	17 (21.3)
Plate fracture	21 (26.3)
Plate dislocation	7 (8.8)

Values are presented as mean±standard deviation or number (%). ^{a)}SternaLock Blu Plate (Zimmer Biomet Inc), ARIX Sternal & Rib System (Jeil Medical Corp), APIS Rib Locking Plate System (TDM Corp), and MatrixRIB Plate (Depuy Synthes).

(78.8%), and screw loosening (73.8%) was the most common mode of failure. The ARIX plating system was used more frequently, resulting in HF. By location, 42.4% lateral screw loosening, 52.9% anterior screw migration, 47.6% posterolateral plate fractures, and 57.1% anterior plate dislocations were recorded. In addition, the ARIX system in the anterolateral sector and the SternaLock system in the posterior sector failed. Screw loosening, screw migration, and plate fractures were more common in the ARIX system (Table 3). However, there was no statistically significant correlation between the failure location, failed plate, and failure mode. Although up to 80% of the HF cases occurred in the ARIX and SternaLock systems, the correlation was not statistically significant (P = 0.12 and P = 0.29, respectively). There was no definitive relationship between anterolateral location and HF (P = 0.70 and P = 0.80, respectively) (Table 4). Furthermore, screw failure occurred in 12 of the 14 patients (85.7%) who underwent costal fixation; however, the difference was not statistically significant (P = 0.33).

Comparison of patients' characteristics according to plate removal surgery

Table 5 demonstrates the differences between patients with HF who underwent reoperation (the plate removal surgery group) and those who did not undergo reoperation. The reoperation group was statistically significantly younger $(59.1 \pm 12.8 \text{ years vs.})$

Variable	Failure location				Failed plating systema)			
variable	Anterior	Lateral	Posterior	Sternum	SternaLock	ARIX	APIS	MatrixRIB
Failure mode								
Screw loosening	22 (37.3)	25 (42.4)	11 (18.6)	7 (11.9)	17 (28.8)	37 (62.7)	7 (11.8)	0
Screw migration	9 (52.9)	6 (35.3)	4 (23.5)	1 (5.9)	5 (29.4)	10 (58.8)	3 (17.6)	0
Plate fracture	5 (23.8)	10 (47.6)	10 (47.6)	0	8 (38.1)	10 (47.6)	4 (19.0)	1 (4.8)
Plate dislocation	4 (57.1)	2 (28.6)	2 (28.6)	0	4 (57.1)	3 (42.9)	1 (14.3)	0
Failure location								
Anterior	-	-	-	-	11 (39.3)	17 (60.7)	3 (10.7)	0
Lateral	-	-	-	-	8 (22.9)	21 (60.0)	6 (17.1)	0
Posterior	-	-	-	-	9 (50.0)	7 (38.9)	3 (16.7)	1 (5.6)
Sternum	-	-	-	-	3 (42.9)	4 (57.1)	0	0

Table 3. Detailed frequency of hardware failures according to location, plating system, and mode

Values are presented as number (%).

^a/SternaLock Blu Plate (Zimmer Biomet Inc), ARIX Sternal & Rib System (Jeil Medical Corp), APIS Rib Locking Plate System (TDM Corp), and MatrixRIB Plate (Depuy Synthes).

Table 4. Relationship between the location of hardware failure, failed plating system, and mode

Variable	SternaLock and ARIX	P-value	APIS and Matrix RIB	P-value	Anterolateral	P-value	Posterior	P-value
Screw failure (n=59)	54 (91.5)	0.12	7 (8.8)	0.46	45 (76.3)	0.70	14 (23.7)	0.10
Plate failure (n=27)	22 (81.5)	0.29	6 (7.5)	0.16	20 (74.1)	0.80	10 (37.0)	0.09

Values are presented as numbers (%). Failed plating systems are SternaLock Blu Plate (Zimmer Biomet Inc), ARIX Sternal & Rib System (Jeil Medical Corp), APIS Rib Locking Plate System (TDM Corp), and MatrixRIB Plate (Depuy Synthes).

49.1 ± 13.3 years, P = 0.03), had fewer fractures (10.0 ± 4.6 vs. 7.2 ± 5.0, P = 0.01), and had more costal fixation (11.8% vs. 80.9%, P = 0.04). SSRF performed at another location on the chest wall was more common in patients who did not undergo reoperation (67.8% vs. 47.6%, P=0.03). Although there was no difference in the failure mode or plating system between the two groups, the failure location, especially in the anterior sternum, was frequent in the reoperation group (P=0.007). The time to detect HF was not different, but the follow-up duration was longer in reoperation group (312.8 ± 244.7 vs. 487.3 ± 371.4 , P=0.01). There were no significant differences in wound infection, subjective chest symptoms, or lung capacity at the last follow-up. A total of 52.4% of patients with plate removal surgery experienced chronic chest pain; however, no statistically significant difference was noted between the groups (P=0.13) (Fig. 4).

ROC analysis

ROC curve analyses were performed on the variables that identified differences according to the plate removal surgery. Using a single-factor evaluation, AUC was low: follow-up duration, last functional vital capacity (FVC), time to SSRF, ISS, number of fractured ribs, number of implanted plates, and age showed AUCs of 0.647, 0.609, 0.431, 0.477, 0.331, 0.354, and 0.337, respectively (Fig. 5).

DISCUSSION

This is the first study to describe the incidence and clinical features of HF after SSRF in a contemporary cohort of level I regional trauma centers in Korea. We found that the overall incidence of HF after SSRF was 10.9% (80 of 728) over the 7 years. Screw failure was the most common type of HF, followed by plate fractures and plate dislocations. HF frequently occurs in the anterolateral region, including the costal cartilage. Half of these patients experienced subjective symptoms, and only 26.3% underwent plate removal surgery. Plate removal was associated with a younger age, fewer fixed ribs, failure location in the anterior region, especially in the costal cartilage portion, and a long follow-up duration. There was no relationship among the failure mode, failure location, and plating system.

SSRF has become increasingly popular in recent years as multiple studies have demonstrated its benefits, even in nonfrail rib fractures [7–10,20]. As the indications for SSRF have expanded, it has become essential to identify and analyze the long-term surgical complications associated with this procedure. Since its inception in the early 21st century, there have been only a few case reports or single-center studies of implant-related complications [21–27]. In 2019, the CWIS published a multicenter retrospective study reporting a 3% (38 of 1,224) HF rate after SSRF, mainly due

Table 5. Comparison of patients according to plate removal

Variable	No (n=59)	Yes (n=21)	P-value
Age (yr)	59.1±12.8	49.1±13.3	0.030
Male sex	49 (83.1)	17 (80.9)	-
Motor vehicle accident	34 (57.6)	12 (57.1)	-
njury severity			
Injury Severity Score	23.5±9.0	21.5±12.7	-
Flail segment	50 (84.7)	9 (42.8)	0.010
Bilateral rib fracture	25 (42.4)	6 (28.6)	-
Sternal fracture	9 (15.3)	5 (23.8)	-
No. of rib fractures	10.0±4.6	7.2±5.0	0.010
Surgical procedure			
Time from admission to SRF (day)	8.0±7.0	6.1±4.4	-
No. of fixed ribs	4.5±1.7	4.1±2.8	-
No. of implanted plates	6.8±3.4	5.9±5.9	0.050
Fixation of costal cartilage	7 (11.8)	17 (80.9)	0.040
Fixation sector of chest wall	, (11.0)	2, (00.2)	0.030
Anterior	6 (10.2)	4 (19.0)	0.000
Lateral	7 (11.8)	4 (19.0) 2 (9.5)	
Posterior	6 (10.2)	2 (9.5) 2 (9.5)	
Combined	40 (67.8)	10 (47.6)	
Sternum (isolated)	40 (07.8)	3 (14.3)	
HF	0	5 (14.5)	
Failure mode			
Screw loosening	42 (71.2)	17 (80.9)	-
Screw migration	7 (11.8)	0	
Plate fracture	13 (22.0)	8 (38.1)	
Plate dislocation			
	12 (20.3)	5 (23.8)	0.060
Failed plating system ^{a)} SternaLock	10 (22 2)	0 (20 1)	0.060
	19 (32.2)	8 (38.1)	
ARIX	33 (55.9)	12 (57.1)	
APIS	8 (13.6)	2 (9.5)	
MatrixRIB	0	1 (4.8)	=
Failure location			0.007
Anterior	18 (30.5)	10 (47.6)	
Lateral	31 (52.5)	4 (19.0)	
Posterior	11 (18.6)	7 (33.3)	
Sternum	2 (3.4)	5 (23.8)	
Complication			
Wound infection	6 (10.2)	14 (66.7)	-
Pneumonia	34 (57.6)	7 (33.3)	-
Acute kidney injury	11 (18.6)	2 (9.5)	-
Tracheostomy	26 (44.1)	3 (14.3)	0.018
Hospital stay (day)	53.2±61.3	49.2±79.6	-
Patients' follow-up			
Time to detection HF	62.8±96.8	143.9 ± 189.0	-
Follow-up duration (day)	312.8±244.7	487.3±371.4	0.010
Subjective chest symptoms	27 (45.8)	14 (66.7)	-
FVC ≥80% predicted	19 (32.2)	15 (71.4)	-

Values are presented as mean±standard deviation or number (%).

SRF, surgical rib fixation; HF, hardware failure; FVC, functional vital capacity

^{a)}SternaLock Blu Plate (Zimmer Biomet Inc), ARIX Sternal & Rib System (Jeil Medical Corp), APIS Rib Locking Plate System (TDM Corp), and MatrixRIB Plate (Depuy Synthes).




Fig. 4. Subjective chest symptoms in patients with hardware failure. No statistically significant differences were noted between the groups. SRF, surgical rib fixation.




Fig. 5. Receiver operating characteristics curve analysis for the prediction of plate removal surgery in patients with hardware failure. The area under the curve for follow-up duration was 0.65 ($0.5 \le 95\%$ confidence interval ≤ 0.79), but not statistically significant. FVC, functional vital capacity; SRF, surgical rib fixation.

to screw migration (n = 17, 44.7%) and plate fracture (n = 18, 47.4%) in the posterolateral region. Forty percent of these patients were asymptomatic, and 55% required explantation of the hardware [15]. The authors concluded that HF after SSRF rarely occurs and is clinically insignificant. A systematic review published in 2020 also reported a low HF risk [14]. Through a review

d 173 surgery- and im-

of 1952 SSRF patients, the study reported 173 surgery- and implant-related complications (10.3%). Implant irritation was the most common (n = 65, 6.9%) implant-related complication, and only one patient (0.1%) presented with a plate fracture. The most recent meta-analysis showed similar results, with 4% (range, 3%– 7%) of HF cases reported, including mechanical failure, infection, pain or discomfort, and nonunion [28]. Broken plates were the most common cause of HF, and insufficient patient data precluded the characterization of the failure location and reasons for failure.

The incidence of HF in our study was slightly higher (10.3%) than that reported previously. This difference can be attributed to two factors. First, the detection rate may have increased due to regular follow-up after surgery. Previous multicenter study lacked follow-up imaging protocols, which may have led to underreporting [15]. However, in our center, we followed a specific imaging protocol, including an x-ray check-up 2 weeks after postdischarge and three-dimensional CT imaging at 3, 6, and 12 months after surgery, which could have contributed to the higher detection rate. Second, the surgeon might have played a role, as the four surgeons involved may have differed in ability, experience, and technical selection, such as the number of screws and plate length, based on the fracture pattern. Although the plate locking screw system theoretically leads to more plate fractures or dislocations, the higher screw failure rate in our study could be attributed to technical errors. To minimize technical errors, it is essential to be meticulous during surgery, focusing on details such as bicortical screwing, proper plate fitting on the rib surface, adequate plate length, and reduction in bone defects.

Compared to other orthopedic surgeries, SSRF poses unique technical challenges because immobilization after surgery is not possible. The posterolateral region is known to experience the most stress during respiration, and plate fatigue in this area can result in the fracture or dislocation of the plate [15,29]. We found that plate fracture or dislocation occurred more frequently in the posterolateral region of the chest. However, to better understand the correlation between the location and mode of metal failure, further research on the biomechanics of metal respiration is necessary. In terms of plating systems, we used four distinct locking screw plate systems that varied in terms of metal thickness, shape, and minor deviations. Despite these variations, no correlation between the plating system and the failure modes was observed in this study. Although ARIX occurred more frequently in HF cases, it was deemed insignificant because it was the most commonly used metal.

Among the patients who experienced HF, only 23% under-

JTI

went metal removal surgery. Of these patients, only two underwent removal due to infection, while the rest underwent surgery due to irritation symptoms, such as pain, tightness, or sensitivity to touch, or during surgery to remove metal from other areas, particularly in cases of orthopedic surgery. Metal removal surgery was more common in younger patients, those with fewer rib plates, and in the anterior region, particularly the costal cartilage, than in the nonsurgical group. Elderly patients with multiple areas requiring metal removal surgery may be hesitant to undergo this procedure because of the potential increased surgical risks and associated complications. Given the relatively infrequent occurrence of HF and the low likelihood of subsequent reoperations, the clinical implications of HF are not particularly substantial. However, this is a technical shortcoming; it is essential to follow proper surgical techniques and carefully monitor patients after surgery to minimize the risk of mechanical complications.

Limitations

This study had several limitations. First, as this was a single-center study, it cannot be considered representative of other trauma centers in Korea. Second, the sample size was insufficient to yield statistically significant results. Although we observed a high frequency of screw failure in the anterior region, no significant correlation was found between the associated variables. Therefore, it is imperative to conduct further multicenter studies with a larger patient cohort to elucidate the underlying characteristics of HF in patients undergoing SSRF. Third, this study had several confounding factors. Differences in technical skills, such as the type of plates selected, the length of the plates used, and the number of screws used, may vary among surgeons. Because HF is a technical error, these factors may have influenced the results. Moreover, the frequency of the surgical sites or plating systems cannot be applied uniformly, leading to a selection bias that affects the results. Given the constrained sample size of the four plating systems, it was impractical to establish any discernible variance in HF outcomes attributed to the particular plating system employed. To conduct an investigation in this regard, it would be necessary to perform an analysis incorporating each plating system with a substantial sample size, carried out by a single surgeon.

Conclusions

HF occurred in 10.9% of cases following SSRF, with no observed correlation between the mode, location, or type of plate used. Patients with coastal fractures require special attention. Although not all patients require plate removal surgery, HF is a technical shortcoming requiring increased surgical vigilance. Furthermore, a deeper understanding of respiratory dynamics through additional research is needed to better understand the etiology of HF.

ARTICLE INFORMATION

Author contributions

Conceptualization: Seon Hee K, YK, HMC; Data curation: DYR, CIP, YK; Formal analysis: DYR, SBL, HK, GHK; Funding acquisition: Seon Hee K; Investigation: Sun Hyun K, NHL; Methodology: SBL, CIP, HK; Project administration: Seon Hee K; Writing-original draft: Sun Hyun K, NHL; Writing-review & editing: all authors. All authors read and approved the final manuscript.

Conflicts of interest

Seon Hee Kim and Hohyun Kim are Editorial Board members of the *Journal of Trauma and Injury* but were not involved in the peer reviewer selection, evaluation, or decision process of this article. The authors have no other conflicts of interest to declare.

Funding

This study was supported by a National Research Foundation of Korea (NRF) grant (No.2020R1F1A1052713), funded by the Ministry of Science and ICT of Korea; and Pusan National University Research Grant in 2020.

Data availability

Data of this study are available from the corresponding author upon reasonable request.

Additional information

This study was presented at the 9th Pan-Pacific Trauma Congress (PPTC) in July 2022 in Gyeongju, Korea.

REFERENCES

- Dehghan N, de Mestral C, McKee MD, Schemitsch EH, Nathens A. Flail chest injuries: a review of outcomes and treatment practices from the National Trauma Data Bank. J Trauma Acute Care Surg 2014;76:462–8.
- 2. Chrysou K, Halat G, Hoksch B, Schmid RA, Kocher GJ. Lessons from a large trauma center: impact of blunt chest trauma in polytrauma patients: still a relevant problem? Scand J Trauma Resusc Emerg Med 2017;25:42.
- **3.** Marasco S, Lee G, Summerhayes R, Fitzgerald M, Bailey M. Quality of life after major trauma with multiple rib fractures.

Injury 2015;46:61–5.

- 4. Fabricant L, Ham B, Mullins R, Mayberry J. Prolonged pain and disability are common after rib fractures. Am J Surg 2013;205:511–6.
- 5. Bulger EM, Arneson MA, Mock CN, Jurkovich GJ. Rib fractures in the elderly. J Trauma 2000;48:1040–7.
- 6. Coary R, Skerritt C, Carey A, Rudd S, Shipway D. New horizons in rib fracture management in the older adult. Age Ageing 2020;49:161–7.
- 7. Liu T, Liu P, Chen J, Xie J, Yang F, Liao Y. A randomized controlled trial of surgical rib fixation in polytrauma patients with flail chest. J Surg Res 2019;242:223–30.
- **8.** Marasco SF, Davies AR, Cooper J, et al. Prospective randomized controlled trial of operative rib fixation in traumatic flail chest. J Am Coll Surg 2013;216:924–32.
- **9.** Tanaka H, Yukioka T, Yamaguti Y, et al. Surgical stabilization of internal pneumatic stabilization? A prospective randomized study of management of severe flail chest patients. J Trauma 2002;52:727–32.
- Pieracci FM, Leasia K, Bauman Z, et al. A multicenter, prospective, controlled clinical trial of surgical stabilization of rib fractures in patients with severe, nonflail fracture patterns (Chest Wall Injury Society NONFLAIL). J Trauma Acute Care Surg 2020;88:249–57.
- 11. Kasotakis G, Hasenboehler EA, Streib EW, et al. Operative fixation of rib fractures after blunt trauma: a practice management guideline from the Eastern Association for the Surgery of Trauma. J Trauma Acute Care Surg 2017;82:618–26.
- 12. Kane ED, Jeremitsky E, Pieracci FM, Majercik S, Doben AR. Quantifying and exploring the recent national increase in surgical stabilization of rib fractures. J Trauma Acute Care Surg 2017;83:1047–52.
- Brasel KJ, Moore EE, Albrecht RA, et al. Western Trauma Association critical decisions in trauma: management of rib fractures. J Trauma Acute Care Surg 2017;82:200–3.
- 14. Peek J, Beks RB, Hietbrink F, et al. Complications and outcome after rib fracture fixation: a systematic review. J Trauma Acute Care Surg 2020;89:411–8.
- 15. Sarani B, Allen R, Pieracci FM, et al. Characteristics of hardware failure in patients undergoing surgical stabilization of rib fractures: a Chest Wall Injury Society multicenter study. J Trauma Acute Care Surg 2019;87:1277–81.
- **16.** Peek J, Kremo V, Beks R, et al. Long-term quality of life and functional outcome after rib fracture fixation. Eur J Trauma

Emerg Surg 2022;48:255-64.

- Uchida K, Miyashita M, Kaga S, et al. Long-term outcomes of surgical rib fixation in patients with flail chest and multiple rib fractures. Trauma Surg Acute Care Open 2020;5:e000546.
- Marasco SF, Martin K, Niggemeyer L, Summerhayes R, Fitzgerald M, Bailey M. Impact of rib fixation on quality of life after major trauma with multiple rib fractures. Injury 2019; 50:119–24.
- Edwards JG, Clarke P, Pieracci FM, et al. Taxonomy of multiple rib fractures: results of the chest wall injury society international consensus survey. J Trauma Acute Care Surg 2020; 88:e40–5.
- **20.** Buyukkarabacak YB, Sengul AT, Celik B, et al. The usefulness of early surgical rib stabilization in flail chest. Acta Chir Belg 2015;115:408–13.
- 21. Sawan TG, Nickerson TP, Thiels CA, et al. Load sharing, not load bearing plates: lessons learned from failure of rib fracture stabilization. Am Surg 2016;82:E15–7.
- 22. de Jong MB, Houwert RM, van Heerde S, de Steenwinkel M, Hietbrink F, Leenen LP. Surgical treatment of rib fracture nonunion: a single center experience. Injury 2018;49:599– 603.
- 23. Kim KT, Chang SW. An unexpected fracture of a titanium rib plate in a patient with traumatic brain injury. Trauma Case Rep 2019;24:100254.
- 24. Kazakova T, Tafen M, Wang W, Petrov R. Rescue re-do inline osteosynthesis with wire cerclage for failed rib plating of multilevel rib nonunion. J Cardiothorac Trauma 2019;4:59–62.
- 25. Metsemakers WJ, Kuehl R, Moriarty TF, et al. Infection after fracture fixation: current surgical and microbiological concepts. Injury 2018;49:511–22.
- **26.** Hernandez MC, Reisenauer JS, Aho JM, et al. Bone autograft coupled with locking plates repairs symptomatic rib fracture nonunions. Am Surg 2018;84:844–50.
- 27. Drahos A, Nowack T, Fitzgerald M, Christie DB. Longterm postoperative hardware complications after open rib fixation. Am Surg 2018;Aug;84:e317–9.
- **28.** Choi J, Kaghazchi A, Sun B, Woodward A, Forrester JD. Systematic review and meta-analysis of hardware failure in surgical stabilization of rib fractures: who, what, when, where, and why. J Surg Res 2021;268:190–8.
- **29.** Marasco SF, Sutalo ID, Bui AV. Mode of failure of rib fixation with absorbable plates: a clinical and numerical modeling study. J Trauma 2010;68:1225–33.